B.R. No: 534/14-15, Date: 30/08/2014

Inspection report for the work of : Drilling of 4 no's Borewell & fixing of pump motor and necessary accessories at Abbigere & Chikkasandra in different locations, in Ward no. 12, in SSD

By

Sri. *G.M. Muniyappa*

Inspection Report

Name of Work	:	Drilling of 4 no's Borewell & fixing of pump motor and necessary accessories at Abbigere & Chikkasandra in different locations. in Ward no. 12. in SSD
Work Order	:	No. EE/DD/WO/39/13-14, Dated: 27/06/2014
Agency	:	KRIDL
B.R. No & Dated	:	534/14-15, Date: 30/08/2014
Bill Amount	:	Rs. 27,25,249.61/-
Job Code	:	012-14-000037
P. Code	:	P-2654

Date of Inspection :- 05-07-15

The above said Work Drilling of 4 Nos Bore Wells and Fixing of pump Motors and necessary accessories at Abbigere and Chikkasandra in different location in Ward 12 in SSD. Has been shown by the Concerned AE.

The above said Work have been inspected along with Concerned AE

The Water Supply to the Residential Areas are running Smoothly.

The Records pertaining to Bore Well and the KEB have been Verified.

The Work done is Satisfactory

05/07/15

Ravi. N.K.
AE W-12

G.M.UNIVERSITY
B.E.(ELECT).B.E.(CIVIL)
EXECUTIVE ENGINEER(P.D.
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರಾಜಾಜಿನಗರ, ಬೆಂಗಳೂರು.

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಗಂಗಾಳೂರು